- b. If the noise is still too great for the particular operation, it is recommended that the unit be surrounded with sponge rubber with ventilation cutouts and attention given to temperature rise versus operating time.
- c. In future models of the UPI-10 efforts will be made at the laboratory to decrease the noise, de-emphasizing to a feasible extent unit operating life, efficiency, and form factor.

50X1

OC-E/R&D/AJS/ljm (10 November 1953)

cc: OC-E

0C-0

R&D

Chrono

Dev/s

Reading

Pending

Registry

Declassified in Part - Sanitized Copy Approved for Release 2013/08/14: CIA-RDP78-03424A001300070001-1